

Fig. 1




Fig. 2

3 / 19




Fig. 3




Fig. 4

09/719440

WO 99/66633

PCT/EP99/03992

5 / 19




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11

11 / 19




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18

280	282	284	286	288	290	
		AA	BB	CC	DD	EE
01		B1		1	EEPROM	0x00
02		B2		1	RAM	0x00
03		B3		2	EEPROM	0x01
04		B4		2	RAM	0x01
...		...		...	...	...
...		...		...	...	...
32		B32		1	ROM	0x00
33		B33		1	ROM	0x01
...		...		...	...	...

Fig. 19




Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24